

MEASUREMENT DIRECTION

HOW TO MEASURE STRAPPED TANK TOPS

REVISED 03/01/06

BEFORE MEASURING: REVIEW FIGURE 6 BEFORE MEASURING

SURFACE USED FOR GARMENT MEASURING SHOULD BE CLEAN AND SMOOTH. DO NOT USE FABRIC COVERED SURFACES FOR GARMENT MEASURING.

**LAY GARMENT FLAT ON SURFACE, FACE UP, SMOOTHED WITH NO WRINKLES.
DO NOT STRETCH ANY PART OF THE GARMENT!**

NOTE: A STRAPPED TANK TOP IS DENOTED BY BINDING STRAPS INSTEAD OF BOUND BODY FABRIC AT THE SHOULDERS

REF. CODE	DIMENSION	MEASUREMENT DIRECTIONS
A.	<u>BODY WIDTH:</u>	MEASURE FROM SIDE-TO-SIDE 1" BELOW BOTTOM OF ARMHOLE SEAM
B.	<u>BODY LENGTH CF:*</u>	MEASURE FROM TOP OF CENTER FRONT SEAM TO HEM BOTTOM EDGE
C.	<u>BODY LENGTH HPS:</u>	MEASURE FROM HP JUNCTION OF FRONT NECK/ARMHOLE SEAM TO HEM BOTTOM EDGE
D.	<u>ARMHOLE:**</u>	MEASURE STRAIGHT FROM INSIDE BINDING EDGE TO EDGE.
E.	<u>SHLDR STRAP LENGTH</u>	MEASURE FROM BACK NECK SEAM UP TO STRAP APEX
F.	<u>FRONT NECK DROP:</u>	LAY A STRAIGHT EDGE ACROSS APEX OF SHLDR STRAPS, MEASURE DOWN FROM IMAGINARY LINE OF EDGE TO TOP OF FRONT NECK BINDING
G.	<u>BACK NECK DROP:</u>	LAY A STRAIGHT EDGE ACROSS HPS OF BACK NECK BINDING SEAM, MEASURE DOWN FROM IMAGINARY LINE OF EDGE TO TOP OF BACK NECK BINDING
H.	<u>NECK WIDTH:</u>	MEASURE FROM BACK JUNCTION OF BINDING EDGE ACROSS TO OTHER JUNCTION EDGE
I.	<u>SHOULDER WIDTH</u>	MEASURE HORIZONTALLY AT TOP OF STRAP OUTSIDE EDGE TO EDGE
J.	<u>BINDING WIDTH:</u>	MEASURE FROM FOLD EDGE OF BINDING AT BINDING TO BODY SEAM. SEVERAL MEASUREMENTS SHOULD BE TAKEN AROUND THE NECK TO VERIFY UNIFORMITY OF BINDING. CHECK NECK AND ARMHOLE BINDING.
K.	<u>MID TORSO</u>	MEASURE 8" DOWN FROM CENTER FRONT SEAM, THEN MEASURE WIDTH FROM SIDESEAM TO SIDESEAM
L.	<u>BOTTOM SWEEP</u>	MEASURE WIDTH STRAIGHT ACROSS BOTTOM AT HEM FOLD EDGE
M.	<u>BOTTOM HEM:</u>	MEASURE FROM FOLD EDGE OF HEM TO TOP-MOST STITCH LINE. MEASURE SEVERAL TIMES.
*	CHECK THE SPECIAL INSTRUCTION SECTION OF THE PRODUCTION/QUALITY SPECIFICATIONS. SOME BODY LENGTH MEASUREMENTS ARE TAKEN FROM CENTER BACK NECK.	
**	CHECK THE SPECIAL INSTRUCTION SECTION OF THE PRODUCTION/QUALITY SPECIFICATIONS. SOME ARMHOLE MEASUREMENTS ARE TAKEN IN A STRAIGHT LINE FROM SHOULDER TO BOTTOM OF ARMHOLE.	

NOTE: ALWAYS CHECK THE SPECIAL INSTRUCTIONS SECTION OF THE PROD./QUALITY SPEC. BEFORE MEASURING. SPECIAL DIRECTIONS ARE LISTED FOR ANY DEVIATIONS FROM THE ABOVE STANDARD DIRECTIONS.

REF: QC/MDSTRAPTANK